

Repaired joists at raised floor at new switchgear in mechanical room



Removal of existing wood flooring to deck on 1st floor



Removal of rejected east entry concrete pad




Second pour of new concrete pad at east entry



Ductwork on 1st Floor



Rigging steel beam for operable partition through 1st Floor window.




Rigging steel beam for operable partition through 1st Floor window.



Operable partition track installation




Operable partition track on 1st Floor



Plywood underlayment at removed wood flooring at 1st Floor



Demolition at former cooling tower pad.




Demolition at north entry concrete walkway area



Test pit to uncover secondary wiring ductbank at new north entry canopy



Test pit to uncover secondary wiring ductbank at new north entry canopy



Existing downspout drainage piping at new north entry canopy